


**FIG. 1**  
(System Overview)



***FIG. 2***  
***(MRB Program Manager)***

50



Aircraft: TEST

General

Administration

Maintenance

Line Maint

Program Mgt

Parts

Permissions

Session User: Sinex

DESCRIPTION		Count	MTH	Form#	Hours	Cycles	Months	Revise	View	Checklist
A1		38	23	AC2001	4000	4000		Revise	View	Checklist
A2		66	23	AC2002	4000	4000		Revise	View	Checklist
A3		65	12	AC2003	4000	4000		Revise	View	Checklist
A4		71	12	AC2004	4000	4000		Revise	View	Checklist
A5		62	12	AC2005	4000	4000		Revise	View	Checklist
A6		58	12	AC2006	4000	4000		Revise	View	Checklist
A7		62	15	AC2007	4000	4000		Revise	View	Checklist
A8		75	15	AC2008	4000	4000		Revise	View	Checklist
A9		66	21	AC2009	4000	4000		Revise	View	Checklist
A10		79	21	AC2010	4000	4000		Revise	View	Checklist
A11		57	19	AC2011	4000	4000		Revise	View	Checklist
A12		86	19	AC2012	4000	4000		Revise	View	Checklist
A13		65	18	AC2013	4000	4000		Revise	View	Checklist
A14		69	18	AC2014	4000	4000		Revise	View	Checklist
A15		67	18	AC2015	4000	4000		Revise	View	Checklist
A16		69	18	AC2016	4000	4000		Revise	View	Checklist
A17		63	22	AC2017	4000	4000		Revise	View	Checklist
A18		64	22	AC2018	4000	4000		Revise	View	Checklist
A19		61	16	AC2019	4000	4000		Revise	View	Checklist

52


54

56 58 60 62

64 66 68

FIG. 3





**FIG. 5**  
*(Tracking Manager)*

120



Aircraft: TEST				Session User: SineX			
General		Administration	Maintenance	Program Mgt	Parts	Permissions	
Structures							
Source	DESCRIPTION	Done	Due				
5210-811-01E Interval 800FC	5210-811-01E Passenger/crew entry door visible structure, stops and fittings. Program Interval A2, A5, A11, A17, A8, A14, A20.	8/23/99 dte 22871.1 hrs 23468 cyc	dte hrs 24268 cyc				
5210-811-01I Interval 2400FC	5210-811-01I Passenger/crew entry door internal elements, including stops and fittings. Requires door lining removal. Program Interval 2400FC.	9/26/00 dte 23160.1 hrs 23794 cyc	dte hrs 47794 cyc				
5220-812-01E Interval 8000FC	5220-812-01E Escape hatches visible structure. Program Interval 8000FC.	10/25/99 dte 23152.1 hrs 23789 cyc	dte hrs 31789 cyc				
5220-812-01I Interval 3200FC	5220-812-01I Escape hatch internal elements, including window frame. Requires door lining removal. Program Interval 3200FC.	dte hrs 0 cyc	dte hrs 32000 cyc				
5220-812-02E Interval 1200FC	5220-812-02E Perform external surveillance in escape hatch window frame. Program Interval A3, A8, A13, A18.	10/25/99 dte 23145 hrs 23786 cyc	dte hrs 24986 cyc				
5230-813-01E Interval 4000FC	5230-813-01E Cargo door visible structure. Program Interval 4000FC.	10/25/99 dte 23152.1 hrs 23789 cyc	dte hrs 27789 cyc				
5230-813-01I Interval 8000FC	5230-813-01I Cargo door internal elements including stops and fittings. Requires door lining and access plate removal. Program Interval 8000FC.	10/25/99 dte 23152.1 hrs 23789 cyc	dte hrs 31789 cyc				
5230-813-02E Interval 4000FC	5230-813-02E Cargo door visible stops and fittings. Program Interval A1, A3, A5, A7, A11, A17, A9, A13, A15, A19.	9/19/99 dte 23059.8 hrs 22695 cyc	dte hrs 24085 cyc				

122

124

126


128

130

132

FIG. 6

FIG. 7



**FIG. 8**  
**(DAMP Manager)**





US248 General			Production			Reports			Administration			Crew			Melling		

250

252

US248 General

Crew

Log Off

Roche

254

Get All Tasks

Assignments

Work History

Evaluate N/R

CrewAssign

Activity

Work Locations

Engineering

Shops

Events

Inspection

256

07-58-23316-0-012 W

Mech 1

Maint Task

260

262

258

07-58-23316-C-013 WRITTEN IN ERROR

Mech 1

Maint Task

Radnor

Van

Kennel

ABM

Manly

McVane

Radnor

Anders

Wilson

Maier

Bocha

Wagner

Mech

Kennel

Inspector

Work Card

07-11-5702-023 42 SEVERAL WORK AREAS UNDERSIDE/LEFT TIE ON AREA MARKED

Mech 1

Maint Task

Radnor

Van

Kennel

ABM

Manly

McVane

Radnor

Anders

Wilson

Maier

Bocha

Wagner

Mech

Kennel

Inspector

Work Card

07-15-27500 INSP LEFT SIDE TRAILER

Mech 1

Maint Task

Radnor

Van

Kennel

ABM

Manly

McVane

Radnor

Anders

Wilson

Maier

Bocha

Wagner

Mech

Kennel

Inspector

Work Card

07-15-93854 INSP INSIDE LEFT SIDE TRAILER

Mech 1

Maint Task

Radnor

Van

Kennel

ABM

Manly

McVane

Radnor

Anders

Wilson

Maier

Bocha

Wagner

Mech

Kennel

Inspector

Work Card

07-42-52500-G INSP NOSE COMP AND RAD

Mech 1

Maint Task

Radnor

Van

Kennel

ABM

Manly

McVane

Radnor

Anders

Wilson

Maier

Bocha

Wagner

Mech

Kennel

Inspector

Work Card

FIG. 11a

270





FIG. 11b

280



286

284

282	US248	12-38-25316-C-013				300		304		DATE
288	Workorder C0000141	290	292	294	296	298	302	CREW	304	6/23/2000
306	CLT	REQ 58	EST 1	AGT 0	MECHS 1	PN OFF	15215310	PN ON	SN OFF	SN ON
		STATION		Check if		SSS-SID-SIP				
				SDA		CORR				
				Required		TASK #				
308	DISCREPANCY Reported by WRITTEN IN ERROR G									
310	EVALUATION									
314	WORK IN PROGRESS									
316	Send Component to Shop									
	Repair Reference									
	Milestone: None Initial Inspection Completed Power OFF									

312

FIG. 12

320

TASK CARD

326

328

330

332

334

336

338

339


Aircraft #: N336US		Aircraft S/N: 23230/1200	Hours: 12050	Cycles: 12051	Date 3/15/00	INSP
An inspection and test of the anti collision strobe lights on each CRJ aircraft operated by Airlines, Inc		Task Card # J3-10-00001				MECH
Will be performed on a six month re-inspection basis		Work Order # C0000141				INSP
Documentation of each aircraft anti collision strobe light inspection and test will be made in the appropriate blocks in form #M022RJ (Ref. Appendix C.3), as follows:		Cycles: 12051				MECH
Enter the required aircraft information at the top of the form		Date 3/15/00				INSP
2						MECH

FIG. 13






FIG. 14

390




FIG. 15



FIG. 16


[illegible]

FIG. 17

**FIG. 18**  
**(Auto-Assign)**